

AD-A105 732

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM. COBLESKILL LOWER RESERVOIR DAM (IN--ETC(U)
FEB 80 G KOCH DACW51-79-C-0001
NL

UNCLASSIFIED

1 - 1
AD 5740

END
DATE
FILMED
81
DTIC

AD A105732

LEVEL II

8

MOHAWK RIVER BASIN COBLESKILL LOWER RESERVOIR DAM

SCHOHARIE COUNTY, NEW YORK
INVENTORY NO. N.Y. 657

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

Cobleskill Lower Reservoir Dam (Inventory
Number NY. 657), Mohawk River Basin,
Schoharie County, New York. Phase I
Inspection Report.



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

(15) DACW51-79-C-0001

10 George Koch

STANDARD
OCT 1 1981

D

12931

NEW YORK DISTRICT CORPS OF ENGINEERS

11 FEB 1980

343 110

10 - 19

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A105 732	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Cobleskill Reservoir Dam No. 2 Mohawk River Basin, Schoharie County, N.Y. Inventory No. 657		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) GEORGE KOCH		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233		8. CONTRACT OR GRANT NUMBER(s) DACW51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 5 August 1981
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Cobleskill Reservoir Dam No. 2 Schoharie County Mohawk River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. The examination of documents and the visual inspection of the Cobleskill Reservoir Dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some problem areas which require additional studies to jointly evaluate conditions affecting the dam.		

Using the Corps of Engineers' "screening criteria" for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped for all storms in excess of 14% of the Probable Maximum Flood. The spillway is adjudged as "seriously inadequate" and the dam is assessed as unsafe non-emergency.

The classification "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to loss of life downstream of the dam.

It is, therefore, recommended that within 3 months of notification to the owner, detailed hydrological/hydraulic investigations of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. The results of these investigations will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to safely discharge the outflow from at least the 1/2 Probable Maximum Flood. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC
SELECTED
SEP 19 1981
D

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam; removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
COBLESKILL LOWER RESERVOIR DAM
I.D. No. NY 657 DEC No. 174A-3138A
MOHAWK RIVER BASIN
SCHOHARIE COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	3
2.1 GEOLOGY	3
2.2 SUBSURFACE INVESTIGATION	3
2.3 DAM AND APPURTENANT STRUCTURES	3
2.4 CONSTRUCTION RECORDS	3
2.5 OPERATION RECORDS	3
2.6 EVALUATION	3
3. VISUAL INSPECTION	4
3.1 FINDINGS	4
3.2 EVALUATION OF OBSERVATIONS	5
4. OPERATION AND MAINTENANCE PRODECURES	6
4.1 PROCEDURES	6
4.2 MAINTENANCE OF THE DAM	6
4.3 WARNING SYSTEM	6
4.4 EVALUATION	6

	<u>PAGE NO.</u>	
5	HYDRAULICS/HYDROLOGY	7
5.1	DRAINAGE AREA CHARACTERISTICS	7
5.2	ANALYSIS CRITERIA	7
5.3	SPILLWAY CAPACITY	7
5.4	RESERVOIR CAPACITY	7
5.5	FLOODS OF RECORD	7
5.6	OVERTOPPING POTENTIAL	7
5.7	EVALUATION	7
6	STRUCTURAL STABILITY	9
6.1	EVALUATION OF STRUCTURAL STABILITY	9
7	ASSESSMENT/RECOMMENDATIONS	10
7.1	ASSESSMENT	10
7.2	RECOMMENDATIONS	10

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. REFERENCES
- E. DRAWINGS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Cobleskill Lower Reservoir Dam
State Located: New York
County: Schoharie
Watershed: Mohawk River Basin
Stream: Dow Brook (tributary to
Cobleskill Creek)
Date of Inspection: October 30, 1980

ASSESSMENT

The examination of documents and the visual inspection of the Cobleskill Lower Reservoir Dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some problem areas which require additional studies to jointly evaluate conditions affecting the dam.

Using the Corps of Engineers' "screening criteria" for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped for all storms in excess of 14% of the Probable Maximum Flood. The spillway is adjudged as "seriously inadequate" and the dam is assessed as unsafe non-emergency.

The classification "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to loss of life downstream of the dam.

It is, therefore, recommended that within 3 months of notification to the owner, detailed hydrological/hydraulic investigations of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. The results of these investigations will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to safely discharge the outflow from at least the 1/2 Probable Maximum Flood. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

In addition, the dam has a number of problem areas, which if left uncorrected, have the potential for the development of hazardous conditions and must be corrected within 1 year. The conditions are:

1. Repair gate house and access bridge or replace.
2. Repair or replace deteriorated and collapsed spillway walks.
3. Remove the trees and brush from the slopes of the embankment, abutments, spillway channel, and downstream channel. Provide a periodic cutting and mowing of these surfaces.
4. Backfill and seed the depressions and animal burrows noted:
5. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of all gates and valves. Document this information for future reference.
6. An emergency action plan must be developed.

George Koch

George Koch
Chief, Dam Safety Section
New York State Department
of Environmental Conservation
NY License No. 45937

Approved By:

Michael J. Smith Jr.
Col. W. M. Smith Jr.
New York District Engineer
05 AUG 1981
05 AUG 1981

Date:




PHOTO #1.
OVERVIEW - COBLESKILL LOWER RESERVOIR DAM

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
COBLESKILL LOWER RESERVOIR DAM
I.D. No. NY 657 DEC No. 174A - 3138A
MOHAWK RIVER BASIN
SCHOHARIE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

Evaluation of the existing conditions of the subject dam to identify deficiencies and hazardous conditions, determine if they constitute hazards to human life and property and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The Cobleskill Lower Reservoir Dam is a 26 feet high earth embankment, believed to have a concrete masonry core wall. It creates a 30 acre water supply reservoir for the village of Cobleskill. The impoundment is located on Dow Brook approximately 2 miles southeast of Cobleskill. The slopes of the embankment are 1:2 1/2 upstream and 1:2 downstream. The upstream slope is protected with a one foot thick rip rap facing. The primary spillway is a 20" drop inlet concrete structure adjacent to the gate house located over the original stream channel. The secondary spillway is a 36.5 feet long uncontrolled overflow section. It is of laid up stone construction. The depth of flow available is 2.4 feet before overtopping of the dam occurs. The reservoir is adjacent to the Cobleskill Upper Reservoir located immediately to the west. The water treatment plant is located just below the lower reservoir dam.

b. Location

The dam is located on Dow Brook, a tributary of Cobleskill Creek and Mohawk River approximately 2 miles southeast of Cobleskill, NY.

c. Size

The dam is 26 feet high and impounds 272. acre feet at normal pool elevation. Therefore, it is classified as "small" in size (less than 40 feet in height).

d. Hazard Classification

The dam is classified as high hazard due to its location above several homes in Mineral Springs, NY. The reservoir is also a major part of the Cobleskill, NY water supply system.

e. Ownership

The dam is owned and operated by the Village of Cobleskill, NY 12093. The Water Supervisor, Mr. John Barber was the contact with the village. He can be reached at the Village of Cobleskill, Cobleskill, NY (518) 234-2195.

f. Purpose of the Dam

The dam provides storage for the Cobleskill water supply.

g. Design and Construction History

The dam was constructed in 1886 by Stanton and Doyle Contractors, Cohoes, NY. It was designed by W.N. Roberts.

h. Normal Operating Procedures

Water releases from the Cobleskill Lower Reservoir are normally passed through the intake and into the water supply system. Any excess flow goes through the uncontrolled primary and secondary spillways.

1.3 PERTINENT DATA

a. Drainage Area (Sq. mi.)

1.78

b. Height of Dam (ft.)

26.

c. Discharge at Dam Site (cfs.)

Spillway Total at Top of Dam

454.

Spillway at Auxiliary Spillway Crest

32.

Reservoir Drain

25.

d. Elevation (ft., U.S.G.S.)

Top of Dam

1173.0

Auxiliary Spillway Crest

1170.5

Primary Spillway Crest

1170.0

Low Level Outlet

1150.

e. Storage (acre Feet)

Top of Dam

365.

Auxiliary Spillway Crest

287.

Primary Spillway Crest.

272.

f. Dam

Type: Homogenous earth believed to have a concrete/masonry core wall.

Length (Ft.):

Upstream Slope:

1:2 1/2

Downstream Slope

1:2

Crest Width (ft):

10

g. Spillway

Type: Concrete, drop inlet adjacent to gate house, 20" orifice inlet.

Masonry overflow auxiliary spillway.

Weir length (auxiliary spillway, ft.)

36.5

h. Reservoir Drain

Type: 16" cast iron pipe from the gate house through the embankment.

Maximum Capacity (cfs.)

25.

SECTION 2: ENGINEERING DATA

2.1 GEOLOGY

The Lower Cobleskill Dam is located in the glaciated portion of the Appalachian Uplands (northern extreme of the Appalachian Plateau) physiographic province of New York State. These uplands were formed by the dissection of the uplifted but flat lying sandstones, siltstones, and shales of the Lower and Middle Devonian Period (395 to 365 million years ago.) The plateau surface is represented by flat-topped divides with drainage generally northward toward the Mohawk River.

Glacial cover is generally thin, the deposits of which have resulted from glaciations during the Wisconsin glaciation, approximately 11,000 years ago.

The "Preliminary Brittle Structures Map of New York" prepared by Yngvar W. Isachsen and William G. McKendrea (dated 1977) indicates the presence of a subsurface fault, showing relative movement as inferred from drill hole data, and a topographic linear feature observed on one or more of the following: topographic map, Landsat (ERTS), Skylab, or U-2 photographic product, within the drainage area of the reservoir.

2.2 SUBSURFACE INVESTIGATION

No subsurface investigation could be located for the design of this dam. Two borings were located for the design of the upper dam. These explorations indicate that the soils encountered are varying mixtures of clay, siltsand, and gravel with boulders of glacial till origin. No water table is indicated. The boring logs are included in Appendix E.

2.3 DAM AND APPURTENANT STRUCTURES

The dam was erected in 1886 by Stanton & Doyle contractors, Cohoes, NY. The dam was designed by W.N. Roberts, Engineer. The design of the dam includes an earth embankment located on the right side of a masonry walled spillway.

2.4 CONSTRUCTION RECORDS

No construction records were available.

2.5 OPERATION RECORDS

All operation records are maintained at the treatment plant below the dam.

2.6 EVALUATION

The data presented in this report has been compiled from information obtained from Mr. John Barber, Water Supervisor, Village of Cobleskill, NY, and the NYS DEC files. This information appears adequate and reliable for Phase I Inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the Lower Cobleskill Reservoir Dam and the surrounding watershed was conducted on October 30, 1980. The weather was cloudy and the temperature ranged in the thirties. The reservoir level at the time of the inspection was approximately 4.5 feet below the spillway crest.

b. Embankment

The earth embankment shows no signs of major distress. The downstream slope is irregular and exhibits depressions which have existed for many years as evidenced by the numerous mature trees growing within these areas. Extensive tree and brush growth was observed on the downstream slope at the abutments and along the upper portion of the upstream slope above the riprap. Animal burrows were also evident near the upper portion of the embankment. The crest of the dam appeared to be in good condition. No evidence of seepage was observed on the embankment or beyond the toe of the dam. A valve box was noted at the downstream toe of the embankment which appeared to be in good condition. Additional valves located downstream supply water to the treatment plant.

c. Spillway

The primary drop inlet spillway is in need of maintenance. The masonry walled riprapped bottom auxiliary spillway is in very poor condition. The masonry walls have deteriorated substantially and portions have collapsed. Extensive vegetation was noted in the channel bottom.

d. Downstream Channel

The downstream channel is narrow and heavily vegetated. Muddy water was observed in a ponded area below the spillway. No evidence of seepage was noted and the origin is believed to be related to the previous rain.

e. Reservoir

No sediment or instability problems were reported within the reservoir area.

f. Appurtenant Structures

The gate house intake system and all associated valves are reported to be operational. The structural condition of the gate house and access bridge is very poor. Immediate repairs are required to prevent collapse of the bridge and building.

3.2 EVALUATION OF OBSERVATIONS

The problem areas observed during the inspection and the recommended remedial measures are as follows:

1. The gate house and access bridge are in very poor structural condition. These areas must be repaired as soon as possible.
2. The masonry walls of both the primary and auxiliary spillway have deteriorated and collapsed. The walls must be repaired immediately.
3. Extensive tree and brush growth was observed on the slopes of the embankment, at the abutments, in the spillway channel, and in the downstream channel. Remove this vegetation and provide a program of periodic cutting and mowing of these surfaces.
4. Depressions and animal burrows were noted on the earth embankment. After removal of the vegetation backfill, these areas to provide a uniform slope and seed the exposed soil.
5. Provide a program of periodic inspection and maintenance of the dam and appurtenances including yearly operation and lubrication of all gates and valves. Document this information for future reference.
6. Develop an emergency action plan for notification of downstream residents and the proper governmental authorities.

SECTION 4: OPERATION AND MAINTNEANCE PROCEDURES

4.1 PROCEDURES

The normal water surface elevation is approximated by the crest of the drop inlet spillway. The reservoir level may be lower than the crest if flows to the treatment plant exceed the rate of inflow.

4.2 MAINTENANCE OF THE DAM

Maintneance of the dam is provided by the owner, the Village of Cobleskill, NY. Maintenance is not considered satisfactory as evidenced by the extensive tree and brush growth, deterioration of spillway walls, depressions and animal burrows on the embankment, and deterioration of the gate house and access bridge.

4.3 WARNING SYSTEM

There is no warning system in effect or in preparation.

4.4 EVALUATION

The dam and appurtenances have been maintained in unsatisfactory condition as noted in "Section 3: Visual Inspection".

SECTION 5: HYDRAULICS/HYDROLOGY

5.1 DRAINAGE AREA CHARACTERISTICS

The Cobleskill Lower Dam is located on Dow Brook adjacent to the Upper Reservoir. Dow Brook has a drainage area of 1.78 square miles at the site and a tributary of Cobleskill Creek and Mohawk River. The watershed is primarily wooded with some pasture in the lower, flatter portions. The cover is glacial till and generally thin.

5.2 ANALYSIS CRITERIA

The analysis of the spillway capacity of the dam and storage of the reservoir was performed using the Corps of Engineers HEC-1 computer model. The unit hydrograph was defined by the Snyder Synthetic Unit Hydrograph method, and the Modified Puls routing procedure was incorporated. The Probable Maximum Precipitation (PMP) was 19.5 inches (24 hrs., 200 square miles) from Hydrometeorological Report #33 in accordance with the recommended guidelines of the Corps of Engineers. Several floods (%s of the Probable Maximum Flood (PMF)) were selected for analysis. The full PMF inflow of 3369 cfs was routed through the reservoir and found to produce an outflow of 3355 cfs.

5.3 SPILLWAY CAPACITY

The spillway is a 20" drop inlet structure adjacent to the gate house, the crest elevation is 1170.0 feet U.S.G.S. There is an auxiliary uncontrolled overflow spillway with a crest elevation of 1170.5 feet. There is 2.5 feet of flow through the auxiliary spillway before overtopping occurs. Maximum flow through the primary spillway before the auxiliary spillway begins to flow is 32 cfs. The maximum total spillway capacity is 454 cfs. before dam overtopping.

5.4 RESERVOIR CAPACITY

The reservoir capacity at the crest of the spillway and at the top of the dam are 272 acre feet and 365 acre feet respectively. Surcharge storage between spillway and top of dam is equivalent to 0.98 inches of runoff from the watershed area.

5.5 FLOODS OF RECORD

There are no gaging station located on or near the dam site nor are there any accounts of high flows or levels.

5.6 OVERTOPPING POTENTIAL

The maximum capacity of the spillway before overtopping occurs is 454. cfs, which is 14% of the routed PMF inflow of 3369 cfs. The dam is overtopped by 0.7 feet during the 1/2 PMF of 1684 cfs and 1.3 feet during the full PMF.

5.7 EVALUATION

The spillway is inadequate to pass all storms in excess of 14% of the PMF. According to the Corps of Engineers, this is considered "seriously inadequate". Although the structural stability did not receive a detailed investigation, it appears to be stable under high flow conditions. However, overtopping could cause rapid failure of this structure. In the event of dam failure, the flood wave would pose significant danger to the residents and water treatment plant. The spillway is, therefore, adjudged as seriously inadequate,

and the dam is assessed as unsafe, non-emergency.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

No signs of major distress were observed in connection with the earth embankment. The gate house and access bridge are in very poor condition. The masonry walls of the spillway are deteriorated and portions have collapsed. Depressions and animal burrows were observed on the embankment.

b. Design and Construction Data

No information could be located concerning the structural stability of the embankment portion of the dam.

c. Post Construction Changes

No post construction changes were initiated.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase I Inspection of Lower Cobleskill Reservoir Dam revealed that the spillway is "seriously inadequate", based upon the Corps of Engineers "screening criteria", and outflows from any storm in excess of 14% of the PMF will overtop the dam. This overtopping could cause breaching of the dam and resulting flood-wave would significantly increase the hazard to downstream residents. For these reasons, the dam has been assessed as unsafe, non-emergency.

b. Adequacy of Information

The information reviewed is considered adequate for Phase I Inspection purposes.

c. Need for Additional Investigation

Since the spillway is considered "seriously inadequate", additional hydrologic/hydraulic investigations are required to more accurately determine the site specific characteristics of the watershed. After these investigations have been completed, remedial measures must be initiated to provide spillway capacity sufficient to discharge the outflow from the 1/2 PMF event.

d. Urgency

The additional required investigations must be initiated within 3 months from the date of notification. Within 1 year, remedial measures as a result of these investigations must be initiated, with completion of the measures during the following year. In the interim, develop an emergency action plan for the notification of downstream residents and the proper governmental authorities in the event of overtopping, and provide around-the-clock surveillance of the dam during periods of extremely heavy run-off. The problem areas listed below must be corrected within 1 year from notification.

7.2 RECOMMENDATIONS

1. The results of the aforementioned investigations will determine the appropriate remedial actions required.
2. Repair the gate house and access bridges as soon as possible.
3. Repair the deteriorated and collapsed spillway walls as soon as possible.
4. Remove the trees and brush from the slopes of the embankment, abutments, spillway channel, and downstream channel. Provide a program of periodic cutting and mowing of these surfaces.
5. Backfill and seed the depressions and animal burrows noted on the embankment.
6. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of all gates and valves. Document this information for future reference.
7. The emergency action plan described in Section 7.1 d, should be maintained and periodically updated during the life of the structure.

APPENDIX A

PHOTOGRAPHS




PHOTO #2.
View from western end of embankment.



PHOTO #3.
Auxiliary spillway. Note heavy vegetation and deteriorated walls.



PHOTO #4.
Auxiliary spillway outlet channel.




PHOTO #5.
Downstream slope of embankment. Note heavy tree growth.



PHOTO # 6.
Drain tile located on eastern end of embankment.
No sign of material movement.



PHOTO #7.
Embankment between Cobleskill Upper and
Lower Reservoirs.

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST1) Basic Data

a. General

Name of Dam Cobleskill Lower DAM
Fed. I.D. # NY 657 DEC Dam No. 174A - 3138A
River Basin MOHAWK
Location: Town Cobleskill County SCHENARIE
Stream Name Dow Brook
Tributary of Cobleskill Creek
Latitude (N) 42° 40' Longitude (W) 74° 21'
Type of Dam homogeneous earth fill (possible corewall)
Hazard Category C
Date(s) of Inspection Oct 30, 1980
Weather Conditions cloudy 30's.
Reservoir Level at Time of Inspection 4.5 feet below spillcrest

b. Inspection Personnel R. M'Curty, J. Vetch

c. Persons Contacted (Including Address & Phone No.)

John BARBER, Water Supr.
Village of Cobleskill
Cobleskill NY 12093
(518) 234-2175

d. History:

Date Constructed 1886 Date(s) Reconstructed _____

Designer _____

Constructed By _____

Owner Village of Cobleskill

2) Embankment

a. Characteristics

- (1) Embankment Material homogeneous earth fill
- (2) Cutoff Type ?
- (3) Impervious Core possible concrete/masonry
- (4) Internal Drainage System ?
- (5) Miscellaneous _____

b. Crest

- (1) Vertical Alignment good
- (2) Horizontal Alignment good
- (3) Surface Cracks —
- (4) Miscellaneous some depressions, animal burrows

c. Upstream Slope

- (1) Slope (Estimate) (V:H) _____
- (2) Undesirable Growth or Debris, Animal Burrows much
tree & brush growth
- (3) Sloughing, Subsidence or Depressions

(4) Slope Protection good

(5) Surface Cracks or Movement at Toe none

d. Downstream Slope

(1) Slope (Estimate - V:H) _____

(2) Undesirable Growth or Debris, Animal Burrows both ~~the~~ tree

and brush growth, animal burrows

(3) Sloughing, Subsidence or Depressions depressions (old,

grown in)

(4) Surface Cracks or Movement at Toe none

(5) Seepage none

- some water found @ toe
felt to be local runoff

(6) External Drainage System (Ditches, Trenches; Blanket) need

cleaning out

(7) Condition Around Outlet Structure brush removal

(8) Seepage Beyond Toe none

e. Abutments - Embankment Contact

good

(1) Erosion at Contact none

(2) Seepage Along Contact none

3) Drainage System

a. Description of System ?

b. Condition of System

c. Discharge from Drainage System

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

none.

5) Reservoir

a. Slopes

stable

b. Sedimentation

due to age - heavy sediment

c. Unusual Conditions Which Affect Dam

—

6) Area Downstream of Dam

a. Downstream Hazard (No. of Homes, Highways, etc.)

Mineral Springs

6-8 homes

b. Seepage, Unusual Growth

none

c. Evidence of Movement Beyond Toe of Dam

none

d. Condition of Downstream Channel

heavy brush trees

7) Spillway(s) (Including Discharge Conveyance Channel)

primary & aux in need of repair

a. General

inadequate - in disrepair

b. Condition of Service Spillway

needs maintenance

c. Condition of Auxiliary Spillway & masonry walls falling in
crest grown over with trees & brush

d. Condition of Discharge Conveyance Channel heavy brush & tree
growth, walls caving in

8) Reservoir Drain/Outlet

Type: Pipe ✓ Conduit _____ Other _____

Material: Concrete _____ Metal ✓ Other _____

Size: 16" Length _____

Invert Elevations: Entrance at 1130. Exit _____

Physical Condition (Describe): operable Unobservable ✓

Material: _____

Joints: _____ Alignment _____

Structural Integrity: —

Hydraulic Capability: 25 cfs

Means of Control: Gate _____ Valve ✓ Uncontrolled _____

Operation: Operable ✓ Inoperable _____ Other _____

Present Condition (Describe): is in operation ?

9) Structural

- a. Concrete Surfaces masonry in bad shape
- b. Structural Cracking in spillway and gate house
- c. Movement - Horizontal & Vertical Alignment (Settlement) out spillway walls.
- d. Junctions with Abutments or Embankments good.
- e. Drains - Foundation, Joint, Face ?
- f. Water Passages, Conduits, Sluices —
- g. Seepage or Leakage none apparent.

h. Joints - Construction, etc. repainting necessary

i. Foundation —

j. Abutments good

k. Control Gates operable

l. Approach & Outlet Channels heavy brush & trees

m. Energy Dissipators (Plunge Pool, etc.) none

n. Intake Structures need maintenance

o. Stability good

p. Miscellaneous —

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition

gate house - ~~is~~ badly deteriorated
spillway walls falling in, tree & brush growth.

11) Operation Procedures (Lake Level Regulation):

water supply normally at or below crest.

APPENDIX C

HYDROLOGIC / HYDRAULIC

ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>1173.0</u>	<u>2.38.</u>	<u>365.0</u>
2) Design High Water (Max. Design Pool)	<u> </u>	<u> </u>	<u> </u>
3) Auxiliary Spillway Crest	<u>1170.6</u>	<u>4.32.0</u>	<u>285.0</u>
4) Pool Level with Flashboards	<u> </u>	<u> </u>	<u> </u>
5) Service Spillway Crest	<u>1170.0</u>	<u>3.0</u>	<u>272.0</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>2.</u>
2) Spillway @ Maximum High Water	<u>454.</u>
3) Spillway @ Design High Water	<u> </u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>81.</u>
5) Low Level Outlet	<u>25.</u>
6) Total (of all facilities) @ Maximum High Water	<u>480.</u>
7) Maximum Known Flood	<u> </u>
8) At Time of Inspection	<u> </u>

CREST:

ELEVATION: 1172.0Type: Concrete SpillwayWidth: 36.5 Length: Spillover Location At the downstream end of the channel

SPILLWAY:

SERVICE

AUXILIARY

1172.0 Elevation 1172.5Drop inlet Type over-flow(12 x 12) 20" orifice Width 36.5

Type of Control

✓ Uncontrolled ✓

Controlled:

— Type —
(Flashboards; gate)— Number —— Size/Length —Invert Material stone masonryAnticipated Length
of operating service extended75' 3" D.C. Chute Length Height Between Spillway Crest
& Approach Channel Invert 1.5% slope
(Weir Flow)

HYDROMETEROLOGICAL GAGES:

Type : noneLocation: —

Records:

Date - —Max. Reading - —

FLOOD WATER CONTROL SYSTEM:

Warning System: none

Method of Controlled Releases (mechanisms):

direct water intakes to filtration plant
drain line &

DRAINAGE AREA:

1.76 sq miles

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type:

Acres, heavily wooded forest, pasture, native

Terrain - Relief:

mostly in steep hills, moderate

Surface - Soil:

thin gravel till, heavy vegetation

Runoff Potential (existing or planned extensive alterations to existing (surface or subsurface conditions)

~~none~~ No major changes evident

Potential Sedimentation problem areas (natural or man-made; present or future)

None

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

~~none~~ NONE

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: NONE

Elevation: _____

Reservoir:

Length @ Maximum Pool 1750' (Miles)

Length of Shoreline (@ Spillway Crest) 4000' (Miles)

APPENDIX D

REFERENCES

APPENDIX D

REFERENCES

- 1) U.S. Department of Commerce, Technical Paper No. 40, Rainfall Frequency Atlas of the United States, May 1961.
- 2) U.S. Department of Commerce, Hydrometeorological Report No. 33, Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours; April 1956.
- 3) Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972 (U.S. Department of Agriculture).
- 4) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963.
- 5) T.W. Lambe and R.V. Whitman, Soil Mechanics, John Wiley and Sons, 1965.
- 6) W.D. Thornbury, Principles of Geomorphology, John Wiley and Sons, 1969.
- 7) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
- 8) Cornell University Agriculture Experiment Station (compiled by M.G. Cline and R.L. Marshall), General Soil Map of New York State and Soils of New York Landscapes, Information Bulletin 119, 1977.

APPENDIX E

STABILITY ANALYSIS

Cobleskill Lower Reservoir DAM

DOW BROOK - ADJACENT TO UPPER RES.

$$\text{DRAINAGE AREA: } \frac{12.43 \text{ mi.}^2 (24000)^2}{(144)(43560)} = 1141.4 \text{ ACRES}$$

$$= 1.78 \text{ mi.}^2$$

$$L = 5.50 \frac{(24000)}{12} = 11,000 \text{ ft.} = 2.08 \text{ mi.}$$

$$L_{ca} = 2.45 (2000) = 4,900 \text{ ft.} = 0.93 \text{ mi.}$$

$$\text{Crest ELEVATION} = 1170.0 \text{ ' U.S.G.S.}$$

$$S_z = \frac{2100 - 1170}{11,000} = .08$$

$$S_{Lca} = \frac{1280 - 1170}{4900} = .02$$

$$t_p = C (L \times L_{ca})^{0.3} = 2.0 (2.08 \times 0.93)^{0.3}$$

$$= 2.44 \text{ hr.}$$

$$t_r = \frac{t_p}{5.5} = 0.44 \text{ hr.}$$

$$T_p = t_p + \frac{1}{2} t_r = 2.44 + .22 = 2.66 \text{ hrs.}$$

$$C_p = 0.625$$

RESERVOIR CAPACITY

FROM PLANS

ELEVATION

USGS

AREA

\bar{A}

ΔV

Σ Volume

FROM DAM

1173

341.6

341.0

TOT. TO 88540000 GAL

340.

337.

335.

333.

333

1173

~~1170.0~~ 1170.0

~~1169.0~~ 1169.0

~~1167.0~~ 1166.0

~~1165.0~~ 1164.0

~~1163.0~~ 1162.0

1152.0

31.0

30.7

30.1

29.2

27.1

30.85

30.40

29.65

28.15

~~28.15~~

30.85

91.20

59.30

56.30

363

272

213


156

34

C

Cobleskill Lower Res.

Spillway Capacity



ELEVATIONS from Cobleskill Water Works PLAN MAR. 1934.

primary spillway crest (20" drop inlet) = 341.0 (=) 1170.0
 Auxiliary " " (36.5' overflow) = 341.6 (=) 1170.6
 Top of DAM = 344.0 (=) 1173.0

weir length = 27' - due to trash racks & depressed crest

say $C = 3.1$ weir flow

- $C = .65$ CRIFICE FLOW $A = \pi \left(\frac{15}{12} \right)^2 = 2.18 \text{ ft}^2$

- Prelim $C = .65$ $A = 2.18$ $Q = 1.022$ neg. head

DEL. TOP OF DAM - OUTLET EL. 30 ft.

EL.	H_u	G_u	H_{out}	G_{out}	Q_p	Q_p	H_u	G_u	Q_{out}
30									
30.5	0.5	1.6			227	67			10
31	1	3.2	6.5	2.1					29
31.5	1.5	4.8	6.75	3.2			1.5	7	32
1171	1	8.9	7	3.4			.4	29	59
1172	2		8	3.2			1.4	187	219
1173	3		9	3.4	30	70	2.4	420	454
1174			10	3.6			3.4	709	745

RECOMMEND $C = 12.5$ } $C = 3.1$
 DAM LENGTH $H_u = 600'$ } $C = 3.1$

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

1
1
RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TO
END OF NETWORK

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR HONEYWELL APR 79

 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

RUN DATE 03/05/81

CCBLESKILL LOWER RESERVOIR DAM

NC NHR NMN IDAY THR IMIN HETRC IPLT IPRT NSTAN
 200 0 15 0 0 0 0 0 0
 JOPER 5 0 0 0 0 0 0 0 0
 JOPER 5 0 0 0 0 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED

RTICS= 0.20 0.40 0.50 0.60 0.80 1.00
 NPLAN= 1 NRTID= 6 LRTID= 1

SUR-AREA RUNOFF COMPUTATION

INFLCN FROM SUB-BASIN

1STAQ 1ICMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 1 1 0 0 0 2 C 1 0 0

HYDRO 1UNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 1.78 0. 1.78 0. 0. 0. 0. 0. 0. 0.

PRECIP DATA

SPFE PHS R6 R12 R24 R48 R72 R96
 0. 19.50 111.00 123.00 133.00 142.00 0. 0.

TRSPC COMPUTED BY THE PROGRAM IS 0.600

LOSS DATA
 LROPT STRKR OLTKR RTICL ERASN STRKS RTICK STRTL CNSTL ALSHX RTIMP
 0 0. 0. 1.00 0. 0. 1.00 1.00 0.10 0. 0.

UNIT HYDROGRAPH DATA
 TP= 2.66 CP=0.63 NYA= 0

RECESSION DATA
 STARTQ= -2.00 ORCSN= 2.00 RTICR= 1.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC=11.95 AND R= 9.56 INTERVALS

UNIT HYDROGRAPH 58 END-OF-PERIOD ORIGINATES, LAG= 2.65 HOURS, CP= 0.63 VOL= 1.00
 6. 25. 59. 94. 131. 170. 208. 240. 262. 276.
 281. 275. 255. 229. 206. 186. 167. 151. 136. 122.
 110. 95. 89. 80. 72. 65. 55. 53. 48. 43.
 39. 31. 28. 25. 21. 19. 17. 15. 13. 11.
 14. 12. 11. 10. 9. 8. 7. 6. 5. 4.
 4. 3. 3. 3. 3. 3. 2. 2. 2. 1.

END-OF-PERIOD FLOW

1.01	0.15	1	0.00	0.00	0.00	4.	1.02	1.15	101	0.03	0.00	0.03	0.03	7.
1.01	0.30	2	0.00	0.00	0.00	4.	1.02	1.30	102	0.03	0.00	0.03	0.03	7.
1.01	0.45	3	0.00	0.00	0.00	4.	1.02	1.45	103	0.03	0.00	0.03	0.03	7.
1.01	1.00	4	0.00	0.00	0.00	4.	1.02	2.00	104	0.03	0.00	0.03	0.03	7.
1.01	1.15	5	0.00	0.00	0.00	4.	1.02	2.15	105	0.03	0.00	0.03	0.03	7.
1.01	1.30	6	0.00	0.00	0.00	4.	1.02	2.30	106	0.03	0.00	0.03	0.03	7.
1.01	1.45	7	0.00	0.00	0.00	4.	1.02	2.45	107	0.03	0.00	0.03	0.03	7.
1.01	2.00	8	0.00	0.00	0.00	4.	1.02	3.00	108	0.03	0.00	0.03	0.03	7.
1.01	2.15	9	0.00	0.00	0.00	4.	1.02	3.15	109	0.03	0.00	0.03	0.03	7.
1.01	2.30	10	0.00	0.00	0.00	4.	1.02	3.30	110	0.03	0.00	0.03	0.03	7.
1.01	2.45	11	0.00	0.00	0.00	4.	1.02	3.45	111	0.03	0.00	0.03	0.03	7.
1.01	3.00	12	0.00	0.00	0.00	4.	1.02	4.00	112	0.03	0.00	0.03	0.03	7.
1.01	3.15	13	0.00	0.00	0.00	4.	1.02	4.15	113	0.03	0.00	0.03	0.03	8.
1.01	3.30	14	0.00	0.00	0.00	4.	1.02	4.30	114	0.03	0.00	0.03	0.03	8.
1.01	3.45	15	0.00	0.00	0.00	4.	1.02	4.45	115	0.03	0.00	0.03	0.03	8.
1.01	4.00	16	0.00	0.00	0.00	4.	1.02	5.00	116	0.03	0.00	0.03	0.03	8.
1.01	4.15	17	0.00	0.00	0.00	4.	1.02	5.15	117	0.03	0.00	0.03	0.03	8.
1.01	4.30	18	0.00	0.00	0.00	4.	1.02	5.30	118	0.03	0.00	0.03	0.03	8.
1.01	4.45	19	0.00	0.00	0.00	4.	1.02	5.45	119	0.03	0.00	0.03	0.03	8.
1.01	5.00	20	0.00	0.00	0.00	4.	1.02	6.00	120	0.03	0.00	0.03	0.03	8.
1.01	5.15	21	0.00	0.00	0.00	4.	1.02	6.15	121	0.08	0.05	0.03	0.03	8.
1.01	5.30	22	0.00	0.00	0.00	4.	1.02	6.30	122	0.08	0.05	0.03	0.03	10.
1.01	5.45	23	0.00	0.00	0.00	4.	1.02	6.45	123	0.08	0.05	0.03	0.03	13.
1.01	6.00	24	0.00	0.00	0.00	4.	1.02	7.00	124	0.08	0.05	0.03	0.03	16.
1.01	6.15	25	0.01	0.01	0.01	4.	1.02	7.15	125	0.08	0.05	0.03	0.03	23.
1.01	6.30	26	0.01	0.01	0.01	4.	1.02	7.30	126	0.08	0.05	0.03	0.03	33.
1.01	6.45	27	0.01	0.01	0.01	4.	1.02	7.45	127	0.08	0.05	0.03	0.03	44.
1.01	7.00	28	0.01	0.01	0.01	4.	1.02	8.00	128	0.08	0.05	0.03	0.03	57.
1.01	7.15	29	0.01	0.01	0.01	4.	1.02	8.15	129	0.08	0.05	0.03	0.03	70.
1.01	7.30	30	0.01	0.01	0.01	4.	1.02	8.30	130	0.08	0.05	0.03	0.03	85.
1.01	7.45	31	0.01	0.01	0.01	4.	1.02	8.45	131	0.08	0.05	0.03	0.03	99.
1.01	8.00	32	0.01	0.01	0.01	4.	1.02	9.00	132	0.08	0.05	0.03	0.03	114.
1.01	8.15	33	0.01	0.01	0.01	4.	1.02	9.15	133	0.08	0.05	0.03	0.03	127.
1.01	8.30	34	0.01	0.01	0.01	4.	1.02	9.30	134	0.08	0.05	0.03	0.03	139.
1.01	8.45	35	0.01	0.01	0.01	4.	1.02	9.45	135	0.08	0.05	0.03	0.03	150.
1.01	9.00	36	0.01	0.01	0.01	4.	1.02	10.00	136	0.08	0.05	0.03	0.03	159.
1.01	9.15	37	0.01	0.01	0.01	4.	1.02	10.15	137	0.08	0.05	0.03	0.03	168.
1.01	9.30	38	0.01	0.01	0.01	4.	1.02	10.30	138	0.08	0.05	0.03	0.03	176.
1.01	9.45	39	0.01	0.01	0.01	4.	1.02	10.45	139	0.08	0.05	0.03	0.03	183.
1.01	10.00	40	0.01	0.01	0.01	4.	1.02	11.00	140	0.08	0.05	0.03	0.03	189.
1.01	10.15	41	0.01	0.01	0.01	4.	1.02	11.15	141	0.08	0.05	0.03	0.03	195.
1.01	10.30	42	0.01	0.01	0.01	4.	1.02	11.30	142	0.08	0.05	0.03	0.03	200.
1.01	10.45	43	0.01	0.01	0.01	4.	1.02	11.45	143	0.08	0.05	0.03	0.03	205.
1.01	11.00	44	0.01	0.01	0.01	4.	1.02	12.00	144	0.08	0.05	0.03	0.03	209.
1.01	11.15	45	0.01	0.01	0.01	4.	1.02	12.15	145	0.43	0.41	0.02	0.02	216.
1.01	11.30	46	0.01	0.01	0.01	4.	1.02	12.30	146	0.43	0.41	0.02	0.02	229.
1.01	11.45	47	0.01	0.01	0.01	4.	1.02	12.45	147	0.43	0.41	0.02	0.02	233.
1.01	12.00	48	0.01	0.01	0.01	4.	1.02	13.00	148	0.43	0.41	0.02	0.02	239.
1.01	12.15	49	0.03	0.03	0.03	4.	1.02	13.15	149	0.52	0.49	0.02	0.02	339.
1.01	12.30	50	0.03	0.03	0.03	4.	1.02	13.30	150	0.52	0.49	0.02	0.02	464.
1.01	12.45	51	0.03	0.03	0.03	4.	1.02	13.45	151	0.52	0.49	0.02	0.02	485.
1.01	13.00	52	0.03	0.03	0.03	4.	1.02	14.00	152	0.52	0.49	0.02	0.02	580.
1.01	13.15	53	0.04	0.04	0.04	4.	1.02	14.15	153	0.65	0.62	0.02	0.02	607.
1.01	13.30	54	0.04	0.04	0.04	4.	1.02	14.30	154	0.65	0.62	0.02	0.02	603.
1.01	13.45	55	0.04	0.04	0.04	4.	1.02	14.45	155	0.65	0.62	0.02	0.02	932.
1.01	14.00	56	0.04	0.04	0.04	4.	1.02	15.00	156	0.65	0.62	0.02	0.02	1063.
1.01	14.15	57	0.04	0.04	0.04	4.	1.02	15.15	157	0.66	0.63	0.02	0.02	1193.
1.01	14.30	58	0.04	0.04	0.04	4.	1.02	15.30	158	1.32	1.29	0.03	0.03	1328.
1.01	14.45	59	0.04	0.04	0.04	4.	1.02	15.45	159	3.68	3.66	0.03	0.03	1492.
1.01	15.00	60	0.04	0.04	0.04	4.	1.02	16.00	160	0.92	0.90	0.02	0.02	1701.
1.01	15.15	61	0.04	0.04	0.04	4.	1.02	16.15	161	0.61	0.58	0.02	0.02	1936.
1.01	15.30	62	0.09	0.09	0.09	4.	1.02	16.30	162	0.61	0.58	0.02	0.02	2183.
1.01	15.45	63	0.25	0.25	0.25	4.	1.02	16.45	163	0.61	0.58	0.02	0.02	2433.
1.01	16.00	64	0.06	0.06	0.06	4.	1.02	17.00	164	0.61	0.58	0.02	0.02	2680.
1.01	16.15	65	0.04	0.04	0.04	5.	1.02	17.15	165	0.61	0.58	0.02	0.02	2971.

1.01	16.45	67	0.04	0.02	0.01	1.02	17.45	167	0.40	0.45	0.02	3210.
1.01	17.00	68	0.04	0.02	0.01	1.02	18.00	168	0.40	0.45	0.02	3329.
1.01	17.15	69	0.03	0.01	0.03	1.22	18.15	169	0.04	0.01	0.03	3369.
1.01	17.30	70	0.03	0.01	0.03	1.02	18.30	170	0.04	0.01	0.03	3341.
1.01	17.45	71	0.03	0.01	0.03	1.02	18.45	171	0.04	0.01	0.03	3243.
1.01	18.00	72	0.03	0.01	0.03	1.02	19.00	172	0.04	0.01	0.03	3103.
1.01	18.15	73	0.00	0.00	0.00	1.02	19.15	173	0.04	0.01	0.03	2949.
1.01	18.30	74	0.00	0.00	0.00	1.02	19.30	174	0.04	0.01	0.03	2781.
1.01	18.45	75	0.00	0.00	0.00	1.02	19.45	175	0.04	0.01	0.03	2603.
1.01	19.00	76	0.00	0.00	0.00	1.02	20.00	176	0.04	0.01	0.03	2416.
1.01	19.15	77	0.00	0.00	0.00	1.02	20.15	177	0.04	0.01	0.03	2227.
1.01	19.30	78	0.00	0.00	0.00	1.02	20.30	178	0.04	0.01	0.03	2039.
1.01	19.45	79	0.00	0.00	0.00	1.02	20.45	179	0.04	0.01	0.03	1855.
1.01	20.00	80	0.00	0.00	0.00	1.02	21.00	180	0.04	0.01	0.03	1681.
1.01	20.15	81	0.00	0.00	0.00	1.02	21.15	181	0.04	0.01	0.03	1520.
1.01	20.30	82	0.00	0.00	0.00	1.02	21.30	182	0.04	0.01	0.03	1376.
1.01	20.45	83	0.00	0.00	0.00	1.02	21.45	183	0.04	0.01	0.03	1246.
1.01	21.00	84	0.00	0.00	0.00	1.02	22.00	184	0.04	0.01	0.03	1128.
1.01	21.15	85	0.00	0.00	0.00	1.02	22.15	185	0.04	0.01	0.03	1023.
1.01	21.30	86	0.00	0.00	0.00	1.02	22.30	186	0.04	0.01	0.03	928.
1.01	21.45	87	0.00	0.00	0.00	1.02	22.45	187	0.04	0.01	0.03	842.
1.01	22.00	88	0.00	0.00	0.00	1.02	23.00	188	0.04	0.01	0.03	765.
1.01	22.15	89	0.00	0.00	0.00	1.02	23.15	189	0.04	0.01	0.03	696.
1.01	22.30	90	0.00	0.00	0.00	1.02	23.30	190	0.04	0.01	0.03	634.
1.01	22.45	91	0.00	0.00	0.00	1.02	23.45	191	0.04	0.01	0.03	577.
1.01	23.00	92	0.00	0.00	0.00	1.03	0.	192	0.04	0.01	0.03	526.
1.01	23.15	93	0.00	0.00	0.00	1.03	0.15	193	0.	0.	0.	480.
1.01	23.30	94	0.00	0.00	0.00	1.03	0.30	194	0.	0.	0.	439.
1.01	23.45	95	0.00	0.00	0.00	1.03	0.45	195	0.	0.	0.	401.
1.02	0.	96	0.00	0.00	0.00	1.03	1.00	196	0.	0.	0.	360.
1.02	0.15	97	0.03	0.00	0.03	1.03	1.15	197	0.	0.	0.	334.
1.02	0.30	98	0.03	0.00	0.03	1.03	1.30	198	0.	0.	0.	305.
1.02	0.45	99	0.03	0.00	0.03	1.03	1.45	199	0.	0.	0.	278.
1.02	1.00	100	0.03	0.00	0.03	1.03	2.00	200	0.	0.	0.	252.

SUM 22.15 18.47 3.68 83254.
1563.11 469.11 94.14 2357.69

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3369.	2478.	856.	415.	83055.
95.	70.	24.	12.	2353.
	12.95	17.90	18.09	18.09
	328.92	434.58	459.59	459.59
	1229.	1698.	1717.	1717.
	1516.	2095.	2118.	2118.

CFS
CMS
INCHES
MM
AC-FT
TFOUS CU H

NOV

STATION 1

O.	INFLOW(I), DUTFLOW(O) AND OBSERVED FLOW(*)				PRECIPIT. AND EXCESS(X)	
	400.	800.	1200.	1600.	2000.	2400.
0.	O.	C.	O.	O.	O.	O.
0.15	11
0.30	21
0.45	31
1.00	41
1.15	51
1.30	61
1.45	71
2.00	81
2.15	91
2.30	101
2.45	111
3.00	121
3.15	131
3.30	141
3.45	151
4.00	161
4.15	171
4.30	181
4.45	191
5.00	201
5.15	211
5.30	221
5.45	231
6.00	241
6.15	251
6.30	261
6.45	271
7.00	281
7.15	291
7.30	301
7.45	311
8.00	321
8.15	331
8.30	341
8.45	351
9.00	361
9.15	371
9.30	381
9.45	391
10.00	401
10.15	411
10.30	421
10.45	431
11.00	441
11.15	451
11.30	461
11.45	471
12.00	481
12.15	491
12.30	501
12.45	511
13.00	521
13.15	531
13.30	541
13.45	551

14.15 571
14.30 581
14.45 591
15.00 601
15.15 611
15.30 621
15.45 631
16.00 641
16.15 651
16.30 661
16.45 671
17.00 681
17.15 691
17.30 701
17.45 711
18.00 721
18.15 731
18.30 741
18.45 751
19.00 761
19.15 771
19.30 781
19.45 791
20.00 801
20.15 811
20.30 821
20.45 831
21.00 841
21.15 851
21.30 861
21.45 871
22.00 881
22.15 891
22.30 901
22.45 911
23.00 921
23.15 931
23.30 941
23.45 951
0. 961
0.15 971
0.30 981
0.45 991
1.001001
1.151011
1.301021
1.451031
2.001041
2.151051
2.301061
2.451071
3.001081
3.151091
3.301101
3.451111
4.001121
4.151131
4.301141
4.451151
5.001161
5.151171
5.301181
5.451191
6.001201
6.151211

LLX
LLX
LLX

[illegible]

23.15187.
23.30190.
23.45191.
0. 192.
0.15193.
0.30194.
0.45195.
1.00196.
1.15197.
1.30198.
1.45199.
2.00200.

[illegible][illegible]

STAGE 1170.00 1170.25 1170.50 1170.75 1171.00 1172.00 1173.00 1174.00
 FLOW 0. 10.00 29.00 37.00 59.00 218.00 454.00 745.00
 CAPACITY= 0. 34. 92. 150. 241. 272.
 ELEVATION= 1152. 1162. 1164. 1166. 1169. 1170.
 CREL SPWJD CDM EXPW ELEV CCEL CAREA EXPL
 1170.0 0. 0. 0. 0. 0. 0. 0.

DAM DATA
 TYPEL CQOO EXPD DAMHIC
 1173.0 3.0 1.5 800.

WARNING *** TOP OF DAM, BOTTOM OF BREACH, OR LOW-LEVEL OUTLET IS NOT WITHIN RANGE OF GIVEN ELEVATIONS IN STORAGE-ELEVATION DATA
 BOTTOM OF RESERVOIR ASSUMED TO BE AT 1152.00
 STORAGE-ELEVATION DATA WILL BE EXTRAPOLATED ABOVE ELEVATION 1170.00

STATION 1, PLAN 1, RATIC 1
 END-OF-PERIOD HYDROGRAPH COORDINATES

OUTFLOW		STORAGE	
STAGE	OUTFLOW	STAGE	STORAGE
1170.00	0.	1170.00	0.
1170.25	0.	1170.25	0.
1170.50	0.	1170.50	0.
1170.75	0.	1170.75	0.
1171.00	0.	1171.00	0.
1172.00	0.	1172.00	0.
1173.00	0.	1173.00	0.
1174.00	0.	1174.00	0.
1175.00	0.	1175.00	0.
1176.00	0.	1176.00	0.
1177.00	0.	1177.00	0.
1178.00	0.	1178.00	0.
1179.00	0.	1179.00	0.
1180.00	0.	1180.00	0.
1181.00	0.	1181.00	0.
1182.00	0.	1182.00	0.
1183.00	0.	1183.00	0.
1184.00	0.	1184.00	0.
1185.00	0.	1185.00	0.
1186.00	0.	1186.00	0.
1187.00	0.	1187.00	0.
1188.00	0.	1188.00	0.
1189.00	0.	1189.00	0.
1190.00	0.	1190.00	0.
1191.00	0.	1191.00	0.
1192.00	0.	1192.00	0.
1193.00	0.	1193.00	0.
1194.00	0.	1194.00	0.
1195.00	0.	1195.00	0.
1196.00	0.	1196.00	0.
1197.00	0.	1197.00	0.
1198.00	0.	1198.00	0.
1199.00	0.	1199.00	0.
1200.00	0.	1200.00	0.
1201.00	0.	1201.00	0.
1202.00	0.	1202.00	0.
1203.00	0.	1203.00	0.
1204.00	0.	1204.00	0.
1205.00	0.	1205.00	0.
1206.00	0.	1206.00	0.
1207.00	0.	1207.00	0.
1208.00	0.	1208.00	0.
1209.00	0.	1209.00	0.
1210.00	0.	1210.00	0.
1211.00	0.	1211.00	0.
1212.00	0.	1212.00	0.
1213.00	0.	1213.00	0.
1214.00	0.	1214.00	0.
1215.00	0.	1215.00	0.
1216.00	0.	1216.00	0.
1217.00	0.	1217.00	0.
1218.00	0.	1218.00	0.
1219.00	0.	1219.00	0.
1220.00	0.	1220.00	0.
1221.00	0.	1221.00	0.
1222.00	0.	1222.00	0.
1223.00	0.	1223.00	0.
1224.00	0.	1224.00	0.
1225.00	0.	1225.00	0.
1226.00	0.	1226.00	0.
1227.00	0.	1227.00	0.
1228.00	0.	1228.00	0.
1229.00	0.	1229.00	0.
1230.00	0.	1230.00	0.
1231.00	0.	1231.00	0.
1232.00	0.	1232.00	0.
1233.00	0.	1233.00	0.
1234.00	0.	1234.00	0.
1235.00	0.	1235.00	0.
1236.00	0.	1236.00	0.
1237.00	0.	1237.00	0.
1238.00	0.	1238.00	0.
1239.00	0.	1239.00	0.
1240.00	0.	1240.00	0.
1241.00	0.	1241.00	0.
1242.00	0.	1242.00	0.
1243.00	0.	1243.00	0.
1244.00	0.	1244.00	0.
1245.00	0.	1245.00	0.
1246.00	0.	1246.00	0.
1247.00	0.	1247.00	0.
1248.00	0.	1248.00	0.
1249.00	0.	1249.00	0.
1250.00	0.	1250.00	0.
1251.00	0.	1251.00	0.
1252.00	0.	1252.00	0.
1253.00	0.	1253.00	0.
1254.00	0.	1254.00	0.
1255.00	0.	1255.00	0.
1256.00	0.	1256.00	0.
1257.00	0.	1257.00	0.
1258.00	0.	1258.00	0.
1259.00	0.	1259.00	0.
1260.00	0.	1260.00	0.
1261.00	0.	1261.00	0.
1262.00	0.	1262.00	0.
1263.00	0.	1263.00	0.
1264.00	0.	1264.00	0.
1265.00	0.	1265.00	0.
1266.00	0.	1266.00	0.
1267.00	0.	1267.00	0.
1268.00	0.	1268.00	0.
1269.00	0.	1269.00	0.
1270.00	0.	1270.00	0.
1271.00	0.	1271.00	0.
1272.00	0.	1272.00	0.
1273.00	0.	1273.00	0.
1274.00	0.	1274.00	0.
1275.00	0.	1275.00	0.
1276.00	0.	1276.00	0.
1277.00	0.	1277.00	0.
1278.00	0.	1278.00	0.
1279.00	0.	1279.00	0.
1280.00	0.	1280.00	0.
1281.00	0.	1281.00	0.
1282.00	0.	1282.00	0.
1283.00	0.	1283.00	0.
1284.00	0.	1284.00	0.
1285.00	0.	1285.00	0.
1286.00	0.	1286.00	0.
1287.00	0.	1287.00	0.
1288.00	0.	1288.00	0.
1289.00	0.	1289.00	0.
1290.00	0.	1290.00	0.
1291.00	0.	1291.00	0.
1292.00	0.	1292.00	0.
1293.00	0.	1293.00	0.
1294.00	0.	1294.00	0.
1295.00	0.	1295.00	0.
1296.00	0.	1296.00	0.
1297.00	0.	1297.00	0.
1298.00	0.	1298.00	0.
1299.00	0.	1299.00	0.
1300.00	0.	1300.00	0.

[illegible]

PEAK OUTFLOW IS 627, AT TIME 43.00 HOURS

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CMS	627.	440.	150.	72.	1457.	
INCHES	18.	12.	4.	2.	469.	
		2.30	3.13	3.13	3.13	
MM		58.41	79.42	79.96	79.96	
AC-FT		218.	297.	299.	299.	
T-DLS CU H		269.	366.	368.	368.	

WARNING *** TOP OF DAM, BOTTOM OF BREACH, OR LOW-LEVEL OUTLET IS NOT WITHIN RANGE OF GIVEN ELEVATIONS IN STORAGE-ELEVATION DATA
 BOTTOM OF RESERVOIR ASSUMED TO BE AT 1152.00
 STORAGE-ELEVATION DATA WILL BE EXTRAPOLATED ABOVE ELEVATION 1170.00

STATION 1, PLAN 1, RATIC 2
END-OF-PERIOD HYDROGRAPH COORDINATES

[illegible]

[illegible]

END-OF-PERIOD HYDROGRAPH CURVATES

[illegible][illegible][illegible]

15102
04E91
0E1E4
22017

● ● ● ● ● ● ● ● ● ●

◆ 中国书画函授大学肇庆分校

●●●●●●●●●●

●●●●●●●●●●

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FORMULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS					
					RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6
					0.20	0.40	0.50	0.60	0.80	1.00
HYDROGRAPH AT	1	1.78	1	674.	1347.	1684.	2021.	2655.	3369.	
	{ 8689.19}		(19.08)	(38.15)	(47.69)	(57.23)	(76.31)	(95.39)	
ROUTED TO	1	1.78	1	627.	1341.	1677.	2013.	2684.	3355.	
	{ 8689.19}		(17.74)	(37.97)	(47.48)	(56.95)	(76.00)	(95.00)	

PLAN 1

.....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1170.00 272. 0.	SPILLWAY CREST 1170.00 272. 0.	TCP OF DAM 1173.00 365. 454.	TIME OF MAX OUTFLOW HOURS	CLAYTON CVEN TCP HOURS	MAXIMUM STORAGE AC-FT	MAXIMUM DEPTH OVER DAM	MAXIMUM OUTFLOW CFS	TIME CF FAILURE HOURS
RATIC	MAXIMUM									
CF	RESEVOUR									
PPF	W.S.ELEV									
0.20	1173.17						370.	0.17	627.	
0.40	1173.55						382.	0.55	1341.	
0.50	1173.69						386.	0.69	1677.	
0.60	1173.81						390.	0.81	2013.	
0.80	1174.05						397.	1.05	2684.	
1.00	1174.26						404.	1.26	3355.	

TEST BORING REPORT

HALL & COMPANY, INC., ALBANY, N. Y.

To James Van Deusen Date February 19 63
Cobleskill, NY Job Cobleskill Dam Site

No. <u>1</u>				No. <u>2</u>				No. _____			
	A	B	C		A	B	C		A	B	C
1'	57			1'	37			1'			
2'	42			2'	19			2			
3	20			3	17			3			
4	CLAY, trace fine	26	12 20	4	CLAY, lge stone	37	15 15	4			
5	sand & pebbles	45	25 29	5	brown, dense, damp	34	19 29	5			
6	brown, dense, dry	108		6		31		6			
7		82		7		29		7			
8		79		8		31		8			
9	SAME - gray	88	23 27	9	CLAY, fine med	39	29 30	9			
10		171	32 56	10	sand & gravel	48	35 39	10			
11		300		11	dense, moist	60		11			
12	Refusal -			12		79		12			
13	Drilled thru			13		80		13			
14	no - ider cm -			14	med SAND & GRA	229	37 40	14			
15	bedded in			15	VEL, silt binder	184	51 163	15			
16	SILT, gray, dense			16	dense, moist	119		16			
17	damp, trace fine			17		75		17			
18	sand			18		58		18			
19	SAME		52 50	19	SAME	45	60 49	19			
20			63 71	20		45	50 75	20			
21	Refusal -			21		37		21			
22	drilled dense			22		37		22			
23	hard pan to			23		36		23			
24	25' - sample at			24	SILT, same med	30	39 25	24			
25	13 25 is Med SAND			25	sand & fine gravel	37	29 30	25			
26	ELUVIAL, silt binder			26	dense, damp	42		26			
27	dense, wet			27		48		27			
28				28		39		28			
29	SILT, med SAND		53 56	29	SAME, moist		38 42	29			
30	GRAVEL, gray		64 78	30			63 75	30			
31	dense, damp			31				31			
32				32				32			
33				33				33			
34	Bottom - 30'			34				34			
35				35				35			
36				36				36			
37				37				37			
38				38				38			
39				39				39			
40				40				40			

Depths indicated are from grade level.

Column "A" indicates blows per foot on Casing.

Column "B" indicates blows from 0" to 6" on Sampling Spoon.

Column "C" indicates blows from 6" to 12" on Sampling Spoon.

Weight of Hammer:

300 lbs. on casing; 140# 30" on spoon

Distance of fall:

18 in.

Size of Casing:

2 1/2 in. extra heavy.

Outside dia. of Spoon:

2 in.

Diameter of Sample:

1 3/8 in.

Overall Length of Spoon

36 in.

TEST BORING REPORT

HALL & COMPANY, INC., ALBANY, N. Y.

To James Van Deusen Date February 19 63
Cobleskill, NY Job Cobleskill Dam Site

No. <u>1</u>				No. <u>2</u>				No. _____			
	A	B	C		A	B	C		A	B	C
1'	57			1'	37			1'			
2'	42			2'	19			2'			
3'	20			3'	17			3'			
4'	CLAY, med fine	26	12 20	4'	CLAY, lge stone	37	15 15	4'			
5'	Sand & pebbles	45	25 29	5'	brn. dense, damp	34	19 29	5'			
6'	brn. dense, damp	108		6'		31		6'			
7'		82		7'		29		7'			
8'		29		8'		31		8'			
9'	SAME - med	88	23 27	9'	CLAY, med med	39	29 30	9'			
10'		21	32 56	10'	med dense, damp	48	35 39	10'			
11'		300		11'	dense, moist	60		11'			
12'	Refusal -			12'		79		12'			
13'	Drilled thru			13'		80		13'			
14'	pu-bler cm-			14'	med SAND & GRA	229	37 40	14'			
15'	bedded in			15'	SEC, silt binder	184	51 163	15'			
16'	SILT, med, dense			16'	med, moist	119		16'			
17'	damp, trace fine			17'		75		17'			
18'	med			18'		58		18'			
19'	SAME	52	50	19'	SAME	45	60 49	19'			
20'		63	71	20'		45	50 75	20'			
21'	Refusal -			21'		37		21'			
22'	drilled dense			22'		37		22'			
23'	hard pan to			23'		36		23'			
24'	25' - sample at			24'	SILT, med med	30	39 25	24'			
25'	15 25 15 Med SAND			25'	med fine gravel	37	29 30	25'			
26'	GRAVEL, silt binder			26'	trace, damp	42		26'			
27'	dense, wet			27'		48		27'			
28'				28'		39		28'			
29'	SILT, med SAND	53	56	29'	SAME, moist		38 42	29'			
30'	GRAVEL, med	64	78	30'			63 75	30'			
31'	dense, damp			31'				31'			
32'				32'				32'			
33'				33'				33'			
34'	1x Hum - 36			34'				34'			
35'				35'				35'			
36'				36'				36'			
37'				37'				37'			
38'				38'				38'			
39'				39'				39'			
40'				40'				40'			

Depths indicated are from grade level.

Column "A" indicates blows per foot on Casing.

Column "B" indicates blows from 0" to 6" on Sampling Spoon.

Column "C" indicates blows from 6" to 12" on Sampling Spoon.

Weight of Hammer:

300 lbs. on casing; 140# on spoon

Distance of fall:

18 in.

Size of Casing:

2 1/2 in. extra heavy.

Outside dia. of Spoon:

2 in.

Diameter of Sample:

1 3/8 in.

Overall length of Spoon

36 in.

APPENDIX D

REFERENCES


APPENDIX D

REFERENCES


- 1) U.S. Department of Commerce, Technical Paper No. 40, Rainfall Frequency Atlas of the United States, May 1961,
- 2) U.S. Department of Commerce, Hydrometeorological Report No. 33, Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours; April 1956.
- 3) Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972 (U.S. Department of Agriculture),
- 4) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963.
- 5) T.W. Lambe and R.V. Whitman, Soil Mechanics, John Wiley and Sons, 1965.
- 6) W.D. Thornbury, Principles of Geomorphology, John Wiley and Sons, 1969.
- 7) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
- 8) Cornell University Agriculture Experiment Station (compiled by M.G. Cline and R.L. Marshall), General Soil Map of New York State and Soils of New York Landscapes, Information Bulletin 119, 1977,

APPENDIX E

DRAWINGS




TOPOGRAPHIC MAP



VICINITY MAP

1



2


1047'

Fence

Survey

Base

Line




34+13

8

COBLESKILL WA

4



ER WORKS

RESERVOIR		CAPACITY	
CONTOUR ELEVATION		ACRES	GALLONS
341		31.0	


INLET

22+06.3

344

1300

N 65°-00' E



32.5

30.8

30.9

28.0

30.1

28.9

3410

BERM

3410.7

W5 34107

8

W.B. 34107

246

281/2


219

2230

3250

OVERFLOW 410
B.M. ELEV. 3450

RESERVOIR CONTOUR ELEVATION	CAPACITY	
	ACRES	GALLONS
341	31.2	
340	30.7	1,075,000
337	30.1	3,000,000
335	29.2	9,600,000
333	27.1	10,000,000
332		8,040,000
		8,554,000
USEABLE CAPACITY		547,830,000
TOTAL		106,350,000
SILT		7,550,000



Survey Base Line 1

INLET

14+03.2

31.8

B

H

SCA

816

FENCE 3



D. C. Dow

B


HIGHWAY

SCALE 1 INCH = 50 FEET HOR.
10 " VERT.

12
W. C. RULAND



ARCH 1934



S 10°-00' E 789.7'

1.1 ACRES PURCHASED 1935

N 10°-00' W
502' ±

N 24°-25' W
292' ±

David C. Lawyer

